

MACROTESTG3

PROFESSIONAL MULTIFUNCTIONAL INSTRUMENT FOR ELECTRIC SAFETY TESTING









CODE HV5036PR

MACROTESTG3

PROFESSIONAL MULTIFUNCTIONAL INSTRUMENT FOR ELECTRIC SAFETY TESTING





ELECTRICAL SAFETY TESTING CEI 64-8

- > Differential Tests type A, AC, B, B+, DD and F up to 1A*:
 - General, Selective and Delayed
 - Tests on RCD with split toroid up to 10A**
 - Differential trip time and current
- > Earth Resistance with voltammetric method with 2 or 3 points in TT, TN and IT systems
 - Ground resistivity
 - Overall earth resistance without differential tripping
 - Earth rod resistance via T2100 clamp***
- Insulation resistance up to 1000V DC and protective conductor continuity with 200mA
- > Protective conductor continuity with 10A (with optional EQUITEST accessory)
- > Voltage drop as a percentage on VDROP lines
- > Advanced Loop for measuring line impedance, testing magnetothermal protections, fuses, sizing cables and measuring the assumed short-circuit current.
- Electric parameter measurement in Singlephase installations:
 V, I, W, VAR, VA, PF, Harmonics and THD%
 Phase sequence (SEQ) and leakage current testing with HT96U current clamp.
 Wi Fi connectivity with HTANALYSIST App on

Wi-Fi connectivity with HTANALYSIS[™] App and PC.

 TopView software for data download and report generation

*B up to 300mA

**With optional RCDX10 accessory

***T2100 clamp optional.



TECHNICAL DATA SHEET

TECHNICAL SPECIFICATIONS

TRMS	•
Insulation with test voltages 50, 100, 250, 500, 1000V DC	•
Continuity of protective conductors with 200mA	•
Continuity of protective conductors with 10A	With optional EQUITES accessory
RCD trip time and current, type B, B+, F, A, AC Standard, Selective and Delayed up to 1A	•
Split toroid RCD trip time and current, type B, B+, F, A, AC Standard, Selective and Delayed up to 10A	With optional RCDX10 accessory
Overall earth resistance without differential tripping	•
Earth resistance with voltammetric method	•
ndividual earth rod resistance with clamp	With optional T2100 clamp accessory
Ground resistivity with 4-wire method	•
Loop/Impedance L-L, L-N, L-PE	•
_oop/Impedance L-L, L-N, L-PE with high resolution	With optional IMP57 accessory
Veasurement of percentage voltage drop on line	•
AUTOMATIC test (Ra, RCD, Insulation) in sequence	•
Contact voltage	•
Phase sequence	•
Leakage current measurement	With optional HT96U accessory
Voltage, Current, Active, Reactive, Apparent Power measurement	 (Single-phase system)
Cosphi, Power Factor measurement	 (Single-phase system)
Voltage and current harmonics up to 25a and THD%	•
Measurement category	CAT IV 300V
Environmental parameter measurement (°C,°F, %RH, Lux)	With optional probes
Test with PR400 remote lead	•
Online help on display	•
Optical/USB serial port for connection with PC	•
Integrated Wi-Fi and compatibility with HTANALYSIS app	•

GENERAL SPECIFICATIONS

Dimensions (L x W x H)	225 x 165 x 75mm
Weight (batteries included)	1.2 kg
Operating temperature	0°C ÷ 40°C
Operating humidity	<80% RH
Protection rating	IP40
Power supply	6x1.5V type AA alkaline batteries or 6x1.2V type AA rechargeable NiMH batteries



ACCESSORIES

STANDARD ACCESSORIES

C2033X	Cable with banana, green - black - blue, shuko plug	
UNIVERSALKITG3	Set of 4 cables, 4 alligator clips and 3 black red-green-blue leads	
KITTERRNE	Set of 4 rods and 4 blue-red-green-black cable coils	
PT400	Touchscreen pen	
PR400	Remote lead with START/STOP button	
ZEROLOOP	Accessory for resetting measuring cable resistance	
C2006	Optics/USB connection cable	
VA507	Rigid carrying case	
YABAT0003000	Rechargeable battery type AA NiMH, 1.2V, 6 pieces	
YABAT0004001	External battery charger	
Quick start guide		
Complete user manual and management software available online		

Calibration report

OPTIONAL ACCESSORIES

IMP57	Accessory for measuring high resolution Loop impedance	
T2100	Clamp to measure ground probe resistance	
HT52/05	Probe for measuring temperature/humidity	
HT53L/05	Probe for measuring illuminance (Lux)	
607-IECN	Connector with magnetic termination	
1066-IECN	Connector for cable extensions with banana, 4mm	
НТ4005К	Standard clamp with full scale 200A/IV AC	
HT96U	Standard clamp with full scale 1/100/1000A-1VAC	
BORSA2051	Carry bag	
RCDX10	Accessory for tests on RCD with split toroid	
SP-0400	Set of straps for shoulder instrument use	
EQUITEST	Instrument for measuring continuity with 10A test current	